



Standard vs Ameliorated Application

Great Western Highway - Kelso to Ragland



On this area we applied a Standard Hydromulch application, which failed because there was not enough nutrients in the soil to stabilise the seedbed and allow for germination. As you can see, the batter did not wash away and remained on the surface.



On another section, we applied a Light Compost Blanket. The results were much better and the client requested that the remaining areas be re-treated with this application.

